



Hella Gutmann Solutions AS  
2619 Lillehammer  
TLF: +47 35 93 40 06  
Mail: support@hella-gutmann.no



# Hotline info

## Bil info

Bilmerke:	Volkswagen
Model:	Passat 2,0 TDI CR
Årsmodell:	2012 - 2016
Km stand:	Ikke relevant
Motorkode:	Alle 2,0 TDI CR

## Bilteknisk problem

- Motorlampe lyser
- Glødelampe lyser
- Motor i nødprogram

## Feilkoder

P00AF – Aktuator Modul for turbolader 1 i klem  
P2563 – Positionsføler til ladetryks regulator, urealistisk signal  
P22D2 – Ventil til turbolader, turbine inngang sitter fast i åpen posisjon

Hella Gutmann Solutions AS  
2619 Lillehammer  
TLF: +47 35 93 40 06  
Mail: support@hella-gutmann.no

# Hotline info

**SOLVED**

## Løsning

- Der er deformation eller innsnevring på vakuumslangen til magnetventilen til ladetryksbegrensning (N75)

