



Hella Gutmann Solutions A/S
8800 Viborg
TLF: +45 87 25 56 44
Mail: support@hella-gutmann.dk

Hotline info

Bil info

Bilmärke:	Mercedes
Model:	Sprinter 906 315CDI
Årsmodell:	2007
Km :	125.000
Motorkod:	646.986

Biltekniskt problem

- Motorlampa lyser
- Går periodisk i nödprogram, typisk vid driftsvarm motor 90°C

Felkoder

P2359 – Laddtrycksregulering, funktions fel





Hella Gutmann Solutions A/S
8800 Viborg
TLF: +45 87 25 56 44
Mail: support@hella-gutmann.dk

Hotline info



Lösning

- Insugningsrör otät mellan alu och plast del.

