



Hella Gutmann Solutions A/S
2619 Lillehammer
TLF: +47 35 93 40 06
Mail: support@hella-gutmann.no



Hotline info

Bil info

Bilmerke:	Mini
Model:	Cooper
Årsmodell:	2012
Km stand:	Ikke relevant
Motorkode:	N47-C20A

Bilteknisk problem

- Permanent feil på airbag system.
- Kupelys virker ikke

Feilkoder

37842 (org kode 93D2) – Henvisningslamper, funksjon feiler.
(Kontrolllampe for deaktivering av fremre passasjer airbag, eller ikke spent sikkerhetsbelte).



Hella Gutmann Solutions A/S
2619 Lillehammer
TLF: +47 35 93 40 06
Mail: support@hella-gutmann.no

Hotline info



Løsning

- Uoriginal LED pære på kupelys.
- I det her tilfellet lys over pedaler.
- Sikring til kupelys defekt.

