



Table of Contents

1	Vehicle Coverage Front Camera	3
2	Vehicle Coverage Rear View Camera	9
3	Vehicle Coverage Area View Camera	11
4	Vehicle Coverage Front Radar	13
5	Vehicle Coverage Rear Radar	18
6	Vehicle Coverage Laser Sensor	21
7	Vehicle Coverage Front Corner Radar	22

Status Version	Manufacturer	Model	Year	Calibration required by	Calibration type	Available since version	Notes	Equipment	
								CSC-Tool	Targets
	Volkswagen	Tiguan (AX)	2021 -	#1, #2, #3, #5, #6	dynamic & static	61	dynamic or static calibration possible	yes/no	CSC 1-01
	Volkswagen	Tiguan (CT)	2024 -	#1, #2, #3, #5, #6	dynamic & static	75	Requirement: HGS CSM, static or dynamic calibration possible	yes/no	CSC 1-01
	Volkswagen	Tiguan Allspace (BJ)	2021 -	#1, #2, #3, #5, #6	dynamic & static	65	dynamic or static calibration possible	yes/no	CSC 1-01
	Volkswagen	Tiguan Allspace (BW)	2017 - 2021	#1, #2, #3, #5, #6	static	51	---	yes	CSC 1-01
	Volkswagen	Touareg (7P)	2010 - 2018	#1, #2, #3, #5, #6	static	45	---	yes	CSC 1-01
	Volkswagen	Touareg (CR)	2018 -	#1, #2, #3, #5, #6	static	56	---	yes	CSC 1-01
	Volkswagen	Touran (1T3)	2010 - 2015	#1, #2, #3, #5, #6	static	45	---	yes	CSC 1-01
	Volkswagen	Touran (5T)	2015 -	#1, #2, #3, #5, #6	static	50	---	yes	CSC 1-01
	Volkswagen	T-Roc (A1)	2017 -	#1, #2, #3, #5, #6	static	55	---	yes	CSC 1-01
	Volkswagen	T-Roc (D1)	2022 -	#1, #2, #3, #5, #6	dynamic & static	66	dynamic or static calibration possible	yes/no	CSC 1-01
	Volkswagen	up! (12)	2018 -	#1, #2, #3, #5, #6	static	61	---	yes	CSC 1-01

Status Version	Manufacturer	Model	Year	Calibration required by	Calibration type	Available since version	Equipment for positioning		Equipment for calibration
							CSC-Tool	Rear Cam Kit I Basic profile	Targets
	Volkswagen	Passat (36)	2010 - 2014	#1, #2, #3, #4, #5	static	51	yes	yes	CSC 2-01
	Volkswagen	Passat (3C)	2005 - 2010	#1, #2, #3, #4, #5	static	51	yes	yes	CSC 2-01
	Volkswagen	Passat (3G)	2015 - 2019	#1, #2, #3, #4, #5	static	51	yes	yes	CSC 2-01
	Volkswagen	Passat (CB)	2019 -	#1, #2, #3, #4, #5	static	58	yes	yes	CSC 2-01
	Volkswagen	Passat CC (35)	2008 - 2012	#1, #2, #3, #4, #5	static	51	yes	yes	CSC 2-01
	Volkswagen	Phaeton (3D)	2007 - 2016	#1, #2, #3, #4, #5	static	51	yes	yes	CSC 2-01
	Volkswagen	Sharan (7N)	2010 -	#1, #2, #3, #4, #5	static	51	yes	yes	CSC 2-01
	Volkswagen	T5 (7E/7F)	2009 - 2015	#1, #2, #3, #4, #5	static	51	yes	yes	CSC 2-01
	Volkswagen	T6.1 (SH)	2019 -	#1, #2, #3, #4, #5	static	59	yes	yes	CSC 2-01
	Volkswagen	T7 (ST)	2022 -	#1, #2, #3, #4, #5	static	66	yes	yes	CSC 2-01
	Volkswagen	Tiguan (5N)	2007 - 2016	#1, #2, #3, #4, #5	static	51	yes	yes	CSC 2-01
	Volkswagen	Tiguan (AD)	2016 -	#1, #2, #3, #4, #5	static	51	yes	yes	CSC 2-01
	Volkswagen	Tiguan (AX)	2021 -	#1, #2, #3, #4, #5	static	66	yes	yes	CSC 2-01
	Volkswagen	Tiguan Allspace (BJ)	2021 -	#1, #2, #3, #4, #5	static	66	yes	yes	CSC 2-01
	Volkswagen	Tiguan Allspace (BW)	2017 -	#1, #2, #3, #4, #5	static	54	yes	yes	CSC 2-01
	Volkswagen	Touareg (7L)	2006 - 2010	#1, #2, #3, #4, #5	static	51	yes	yes	CSC 2-01
	Volkswagen	Touareg (7P)	2010 - 2018	#1, #2, #3, #4, #5	static	51	yes	yes	CSC 2-01
	Volkswagen	Touareg (CR)	2018 -	#1, #2, #3, #4, #5	static	56	yes	yes	CSC 2-01

Status Version	Manufacturer	Model	Year	Calibration required by	Calibration type	Available since version	CSC-Tool	Equipment for positioning		Equipment for calibration		
								Rear Cam Kit I Basic profile	Rear Cam Kit I Addition Profile	Rear Cam Kit I Basic reference panel	Rear Cam Kit I Addition reference panel	Reference mat
	Volkswagen	T7 (ST)	2022 -	#1, #2, #3, #4, #5, #6	static	70	no	no	no	no	no	CSC 3-02
	Volkswagen	Tiguan (AD)	2016 - 2021	#1, #2, #3, #4, #5, #6	static	52	yes	no	no	no	no	CSC 3-02
	Volkswagen	Tiguan (AX)	2021 -	#1, #2, #3, #4, #5, #6	static	61	yes	no	no	no	no	CSC 3-02
	Volkswagen	Tiguan Allspace (BJ)	2021 -	#1, #2, #3, #4, #5, #6	static	65	yes	no	no	no	no	CSC 3-02
	Volkswagen	Tiguan Allspace (BW)	2017 - 2021	#1, #2, #3, #4, #5, #6	static	53	yes	no	no	no	no	CSC 3-02
	Volkswagen	Touareg (7P)	2010 - 2018	#1, #2, #3, #4, #5, #6	static	62	yes	yes	yes	CSC 2-01	CSC 3-01	no
	Volkswagen	Touareg (CR)	2018 -	#1, #2, #3, #4, #5, #6	static	56	yes	no	no	no	no	CSC 3-02

Status Version	Manufacturer	Model	Year	Calibration required by	Calibration type	Available since version	Notes	Equipment for positioning		Equipment for calibration		
								CSC-Tool	Rear Cam Kit I Basic profile	Radar reflector	Magnetic laser CSC 4-02	Mirror adjusting device CSC-4-03
	Volkswagen	Golf 8 (CD)	2020 -	#1, #2, #3, #4, #5, #6	dynamic & static	59	static or dynamic calibration possible	yes/no	no	CSC 4-01/CSC 4-01 EVO	no	no
	Volkswagen	Golf 8 Facelift (DA/DB)	2024 -	#1, #2, #3, #4, #5, #6	dynamic & static	75	static or dynamic calibration possible	yes/no	no	CSC 4-01/CSC 4-01 EVO	no	no
	Volkswagen	ID.3 (E1)	2020 -	#1, #2, #3, #4, #5, #6	dynamic & static	60	static or dynamic calibration possible	yes/no	no	CSC 4-01/CSC 4-01 EVO	no	no
	Volkswagen	ID.4 (E2)	2021 -	#1, #2, #3, #4, #5, #6	dynamic & static	61	static or dynamic calibration possible	yes/no	no	CSC 4-01/CSC 4-01 EVO	no	no
	Volkswagen	ID.5 (E3)	2022 -	#1, #2, #3, #4, #5, #6	dynamic & static	66	static or dynamic calibration possible	yes/no	no	CSC 4-01/CSC 4-01 EVO	no	no
	Volkswagen	ID.7 (ED)	2024 -	#1, #2, #3, #4, #5, #6	dynamic & static	75	static or dynamic calibration possible	yes/no	no	CSC 4-01/CSC 4-01 EVO	no	no
	Volkswagen	ID.Buzz (EB)	2022-	#1, #2, #3, #4, #5, #6	dynamic & static	69	---	yes/no	no	CSC 4-01/CSC 4-01 EVO	no	no
	Volkswagen	Passat (36)	2010 - 2014	#1, #2, #3, #4, #5, #6	static	46	---	yes	no	CSC 4-01/CSC 4-01 EVO	yes	no
	Volkswagen	Passat (3C)	2005 - 2010	#1, #2, #3, #4, #5, #6	static	46	---	yes	no	CSC 4-01/CSC 4-01 EVO	yes	no
	Volkswagen	Passat (3G)	2015 - 2019	#1, #2, #3, #4, #5, #6	static	48	---	yes	no	CSC 4-01/CSC 4-01 EVO	no	no
	Volkswagen	Passat (CB)	2019 -	#1, #2, #3, #4, #5, #6	static	58	---	yes	no	CSC 4-01/CSC 4-01 EVO	no	no
	Volkswagen	Passat (CJ)	2024 -	#1, #2, #3, #4, #5, #6	dynamic & static	75	static or dynamic calibration possible	yes/no	no	CSC 4-01/CSC 4-01 EVO	no	no
	Volkswagen	Passat CC (35)	2008 - 2012	#1, #2, #3, #4, #5, #6	static	46	---	yes	no	CSC 4-01/CSC 4-01 EVO	yes	no
	Volkswagen	Phaeton (3D)	2007 - 2016	#1, #2, #3, #4, #5, #6	static	50	---	yes	no	CSC 4-01/CSC 4-01 EVO	yes	no
	Volkswagen	Polo (6C)	2014 - 2017	#1, #2, #3, #4, #5, #6	static	49	---	yes	no	CSC 4-01/CSC 4-01 EVO	no	no
	Volkswagen	Polo (AE)	2021 -	#1, #2, #3, #4, #5, #6	dynamic & static	65	static or dynamic calibration possible	yes/no	no	CSC 4-01/CSC 4-01 EVO	no	no
	Volkswagen	Polo (AW)	2017 - 2021	#1, #2, #3, #4, #5, #6	dynamic & static	53	static or dynamic calibration possible	yes/no	no	CSC 4-01/CSC 4-01 EVO	no	no
	Volkswagen	Sharan (7N)	2010 -	#1, #2, #3, #4, #5, #6	static	49	---	yes	no	CSC 4-01/CSC 4-01 EVO	yes	no
	Volkswagen	T6 (SG/SF)	2015 - 2019	#1, #2, #3, #4, #5, #6	static	49	---	yes	no	CSC 4-01/CSC 4-01 EVO	no	no
	Volkswagen	T6.1 (SH/SJ)	2019 -	#1, #2, #3, #4, #5, #6	dynamic & static	59	static or dynamic calibration possible	yes/no	no	CSC 4-01/CSC 4-01 EVO	no	no
	Volkswagen	T7 (ST)	2022 -	#1, #2, #3, #4, #5, #6	dynamic & static	65	static or dynamic calibration possible	yes/no	no	CSC 4-01/CSC 4-01 EVO	no	no
	Volkswagen	Taigo (CS)	2022 -	#1, #2, #3, #4, #5, #6	dynamic & static	65	static or dynamic calibration possible	yes/no	no	CSC 4-01/CSC 4-01 EVO	no	no
	Volkswagen	T-Cross (C1)	2019 -	#1, #2, #3, #4, #5, #6	dynamic & static	57	static or dynamic calibration possible	yes/no	no	CSC 4-01 EVO	no	no
	Volkswagen	Tiguan (AD)	2016 - 2021	#1, #2, #3, #4, #5, #6	static	51	---	yes	no	CSC 4-01/CSC 4-01 EVO	no	no
	Volkswagen	Tiguan (AX)	2021 -	#1, #2, #3, #4, #5, #6	dynamic & static	61	static or dynamic calibration possible	yes/no	no	CSC 4-01/CSC 4-01 EVO	no	no
	Volkswagen	Tiguan (CT)	2024 -	#1, #2, #3, #4, #5, #6	dynamic & static	75	static or dynamic calibration possible	yes/no	no	CSC 4-01/CSC 4-01 EVO	no	no
	Volkswagen	Tiguan Allspace (BJ)	2021 -	#1, #2, #3, #4, #5, #6	dynamic & static	65	static or dynamic calibration possible	yes/no	no	CSC 4-01/CSC 4-01 EVO	no	no
	Volkswagen	Tiguan Allspace (BW)	2017 -	#1, #2, #3, #4, #5, #6	static	52	---	yes	no	CSC 4-01 EVO	no	no
	Volkswagen	Touareg (7P)	2010 - 2018	#1, #2, #3, #4, #5, #6	static	46	---	yes	no	CSC 4-01/CSC 4-01 EVO	no	no
	Volkswagen	Touareg (CR)	2018 -	#1, #2, #3, #4, #5, #6	static	56	---	yes	no	CSC 4-01 EVO	no	no
	Volkswagen	Touran (5T)	2015 -	#1, #2, #3, #4, #5, #6	static	50	---	yes	no	CSC 4-01/CSC 4-01 EVO	no	no
	Volkswagen	T-Roc (A1)	2017 -	#1, #2, #3, #4, #5, #6	dynamic & static	55	static or dynamic calibration possible	yes/no	no	CSC 4-01/CSC 4-01 EVO	no	no
	Volkswagen	T-Roc (D1)	2022 -	#1, #2, #3, #4, #5, #6	dynamic & static	66	static or dynamic calibration possible	yes/no	no	CSC 4-01/CSC 4-01 EVO	no	no

Status Version	Manufacturer	Model	Year	Calibration required by	Calibration type	Available since version	Notes	Equipment for positioning					Equipment for calibration
								CSC-Tool	Rear Cam Kit I Basic Profile	Rear Cam Kit I Basic reference panel	Rear Cam Kit I Addition Profile	Positioning aid	Radar reflector
	Mercedes	EQE SUV (BM294)	2023-	#1,#2,#3,#4,#5,#6	dynamic	72	Precondition: SGW activation via HGS Cyber Security Management and the mega macs X (DoIP)	no	no	no	no	no	no
	Mercedes	EQS-SUV (BM296)	2022-	#1,#2,#3,#4,#5,6	dynamic	69	Precondition: SGW activation via HGS CSM and mega macs X (DoIP)	no	no	no	no	no	no
	Mercedes	G-Class (BM463)	2018 -	#1, #2, #5	dynamic	70	---	no	no	no	no	no	no
	Mercedes	GLA-Class (BM247)	2020 -	#1, #2, #5	dynamic	60	---	no	no	no	no	no	no
	Mercedes	GLB-Class (BM247)	2019 -	#1, #2, #5	dynamic	59	---	no	no	no	no	no	no
	Mercedes	GLC-Class (BM254)	2022-	#1, #2, #3, #4,5,6	dynamic	68	Precondition: SGW activation via HGS CSM and mega macs X (DoIP)	no	no	no	no	no	no
	Mercedes	GLE/GLS-Class (BM167)	2018 -	#1, #2, #5	dynamic	59	---	no	no	no	no	no	no
	Mercedes	T-Class (BM420)	2022-	#1,#2,#3,#4,#5,6	dynamic	69	---	no	no	no	no	no	no
	Mitsubishi	ASX	2018 -	#1, #2, #3, #5, #6	static	62	---	yes	yes	no	no	yes	CSC 4-07
	Mitsubishi	EclipseCross	2019 -	#1, #2, #3, #5, #6	static	62	---	yes	yes	no	no	yes	CSC 4-07
	Mitsubishi	L200	2019 -	#1, #2, #3, #5, #6	static	62	---	yes	yes	no	no	yes	CSC 4-07
	Mitsubishi	Outlander III	2019 -	#1, #2, #3, #5, #6	static	62	---	yes	yes	no	no	yes	CSC 4-07
	Peugeot	308III	2022-	#1, #2, #3, #5, #6	dynamic	69	---	no	no	no	no	no	no
	Renault	Arkana	2020 -	#1, #2, #5, #6	dynamic	66	Precondition: SGW activation via HGS Cyber Security Management or OEM portal and the use of the PassThru function via the VCI.	no	no	no	no	no	no
	Renault	Austral	2022 -	#1, #2, #3, 4#, #5, 6	dynamic	75	Precondition: SGW activation via HGS Cyber Security Management or OEM portal and the use of the PassThru function via the VCI.	no	no	no	no	no	no
	Renault	Captur II	2019 -	#1, #2, #5, #6	dynamic	60	Precondition: SGW activation via HGS CSM or OEM portal with PassThru function via VCI.	no	no	no	no	no	no
	Renault	Clio V	2019 -	#1, #2, #5, #6	dynamic	60	Precondition: SGW activation via HGS CSM or OEM portal with PassThru function via VCI.	no	no	no	no	no	no
	Renault	Espace-V Facelift	2020-	#1, #2, #5, #6	dynamic	68	Precondition: SGW activation via HGS CSM or OEM portal with PassThru function via VCI.	no	no	no	no	no	no
	Renault	Kangoo III	2021 -	#1, #2, #3, #5, #6	dynamic	71	Precondition: SGW activation via HGS CSM or OEM portal with PassThru function via VCI.	no	no	no	no	no	no
	Renault	Kangoo-III e-Tech Electric	2022 -	#1, #2, #3, 4#, #5, #6	dynamic	74	Precondition: SGW activation via HGS Cyber Security Management or OEM portal and the use of the PassThru function via the VCI.	no	no	no	no	no	no
	Renault	Megane e-Tech Electric	2021 -	#1, #2, #5, #6	dynamic	73	Precondition: SGW activation via HGS Cyber Security Management	no	no	no	no	no	no
	Renault	Megane IV Facelift	2018 -	#1, #2, #5, #6	dynamic	62	Precondition: SGW activation via HGS CSM or OEM portal with PassThru function via VCI.	no	no	no	no	no	no
	Renault	Talisman Facelift	2018 -	#1, #2, #5, #6	dynamic	62	Precondition: SGW activation via HGS CSM or OEM portal with PassThru function via VCI.	no	no	no	no	no	no
New in V76	Seat	Alhambra	2016-2023	#1, #2, #3, #5, #6	static	76	---	yes	yes	CSC 2-01	yes	no	CSC 4-06
New in V76	Seat	Ateca	2017-2023	#1, #2, #3, #5, #6	static	76	---	yes	yes	CSC 2-01	yes	no	CSC 4-06
New in V76	Subaru	Crosstrek/Impreza	2024 -	#1, #2,#3,#5	static	76	OEM/IAM equipment is required for alignment	no	no	no	no	yes	CSC 4-05
New in V76	Subaru	Forester	2023 -	#1, #2,#3,#5	static	76	OEM/IAM equipment is required for alignment	no	no	no	no	yes	CSC 4-05
New in V76	Subaru	Forester	2015-2020	#1, #2,#3,#5	static	76	OEM/IAM equipment is required for alignment	no	no	no	no	yes	CSC 4-05
New in V76	Subaru	Impreza	2020-2023	#1, #2,#3,#5	static	76	OEM/IAM equipment is required for alignment	no	no	no	no	yes	CSC 4-05
New in V76	Subaru	Impreza	2017-2020	#1, #2,#3,#5	static	76	OEM/IAM equipment is required for alignment	no	no	no	no	yes	CSC 4-05
New in V76	Subaru	Levorg	2019-2020	#1, #2,#3,#5	static	76	OEM/IAM equipment is required for alignment	no	no	no	no	yes	CSC 4-05
New in V76	Subaru	Outback	2018-2021	#1, #2,#3,#5	static	76	OEM/IAM equipment is required for alignment	no	no	no	no	yes	CSC 4-05
	Subaru	Solterra	2022 -	#1, #2, #3, #5, #6	static	72	---	yes	yes	no	no	yes	CSC 4-05
New in V76	Subaru	XV	2018-2020	#1, #2,#3,#5	static	76	OEM/IAM equipment is required for alignment	no	no	no	no	yes	CSC 4-05
New in V76	Subaru	XV	2021 -	#1, #2,#3,#5	static	76	OEM/IAM equipment is required for alignment	no	no	no	no	yes	CSC 4-05
	Suzuki	S-Cross	2022-	#1, #2, #3, #4, #5, #6	static	70	OEM/IAM equipment is required for alignment	no	no	no	no	no	no
	Suzuki	Swace	2023-	#1, #2, #3, #5, #6	static	74	---	yes	yes	no	no	yes	CSC 4-05
	Suzuki	Swace	2020 -	#1, #2, #5	static	62	---	yes	yes	no	no	yes	CSC 4-05
	Suzuki	Swift Sport	2020-	#1, #2, #3, #4, #5, #6	static	67	OEM/IAM equipment is required for alignment	no	no	no	no	no	no
	Suzuki	Vitara	2019-	#1, #2, #3, #4,5,6	static	67	OEM/IAM equipment is required for alignment	no	no	no	no	no	no
	Suzuki	bZ4X	2022 -	#1, #2, #5	static	71	---	yes	yes	no	no	yes	CSC 4-05
	Toyota	Camry	2021-	#1 #2 #3 #4 5 #6	static	65	---	yes	yes	no	no	yes	CSC 4-05
	Toyota	C-HR	2023 -	#1, #2, #3, #5, #6	static	74	---	yes	yes	no	no	yes	CSC 4-05
	Toyota	C-HR	2016 - 2020	#1, #2, #5	static	57	---	yes	yes	no	no	yes	CSC 4-05
	Toyota	C-HR	2020 -	#1, #2, #5	static	62	---	yes	yes	no	no	yes	CSC 4-05
	Toyota	Corolla	2018 -	#1, #2, #5	static	58	---	yes	yes	no	no	yes	CSC 4-05
	Toyota	Corolla Cross	2022 -	#1, #2, #5	static	70	---	yes	yes	no	no	yes	CSC 4-05
	Toyota	Corolla Hybrid	2023 -	#1, #2, #3, #5, #6	static	72	---	yes	yes	no	no	yes	CSC 4-05
	Toyota	Corolla sedan	2018 -	#1, #2, #5	static	60	---	yes	yes	no	no	yes	CSC 4-05
	Toyota	Hiace	2019 -	#1, #2, #5	static	61	only model variant Australia	yes	yes	no	no	yes	CSC 4-05
	Toyota	Highlander	2018 - 2020	#1, #2, #5	static	58	---	yes	yes	no	no	yes	CSC 4-05
	Toyota	Highlander	2020 -	#1, #2, #5	static	62	---	yes	yes	no	no	yes	CSC 4-05
	Toyota	Land Cruiser	2016 - 2020	#1, #2, #5	static	58	---	yes	yes	no	no	yes	CSC 4-05
	Toyota	Land Cruiser Prado	2020 -	#1, #2, #5	static	62	---	yes	yes	no	no	yes	CSC 4-05
	Toyota	Mirai	2021 -	#1, #2, #5	static	71	---	yes	yes	no	no	yes	CSC 4-05
	Toyota	Prius	2016 -	#1, #2, #5	static	58	---	yes	yes	no	no	yes	CSC 4-05
	Toyota	Prius	2020-	#1, #2, #5	static	63	---	yes	yes	no	no	yes	CSC 4-05
	Toyota	Prius PHV Plug-In Hybrid	2020-	#1, #2, #5	static	63	---	yes	yes	no	no	yes	CSC 4-05
	Toyota	Prius Plug-In Hybrid	2023 -	#1, #2, #3, #5, #6	static	72	---	yes	yes	no	no	yes	CSC 4-05
	Toyota	RAV4	2016 - 2018	#1, #2, #5	static	58	---	yes	yes	no	no	yes	CSC 4-05
	Toyota	RAV4	2018 -	#1, #2, #5	static	58	---	yes	yes	CSC 2-01	yes	yes	CSC 4-05

Status Version	Manufacturer	Model	Year	Calibration required by	Calibration type	Available since version	Notes	Equipment for positioning					Equipment for calibration
								CSC-Tool	Rear Cam Kit I Basic Profile	Rear Cam Kit I Basic reference panel	Rear Cam Kit I Addition Profile	Positioning aid	Radar reflector
	Toyota	RAV4 Plug-In	2020-	#1, #2, #5,	static	68	---	yes	yes	no	no	yes	CSC 4-05
New in V76	Toyota	Yaris	2024 -	#1, #2,#3,#5	static	76	---	yes	yes	no	no	yes	CSC 4-05
New in V76	Toyota	Yaris	2024 -	#1, #2,#3,#5	static	76	---	yes	yes	no	no	yes	CSC 4-05
	Toyota	Yaris	2020-	#1, #2, #5,	static	68	---	yes	yes	no	no	yes	CSC 4-05
	Toyota	Yaris GR	2020-	#1, #2, #5,	static	68	---	yes	yes	no	no	yes	CSC 4-05
	Volkswagen	Arteon (3H)	2017 -	#1, #2, #3, #5, #6	static	57	---	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Volkswagen	CC (35)	2012 - 2017	#1, #2, #3, #5, #6	static	57	---	yes	yes	CSC 2-01	yes	no	CSC 4-06
New in V76	Volkswagen	Crafter	2017 -	#1, #2, #3, #5, #6	static	76	---	yes	yes	CSC 2-01	yes	no	CSC 4-06
New in V76	Volkswagen	Golf7	2015 - 2020	#1, #2, #3, #5, #6	static	76	---	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Volkswagen	Passat (36)	2010 - 2014	#1, #2, #3, #5, #6	static	57	---	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Volkswagen	Passat (3G)	2015 - 2019	#1, #2, #3, #5, #6	static	57	---	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Volkswagen	Passat (CB)	2019 -	#1, #2, #3, #5, #6	static	58	---	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Volkswagen	Passat CC (35)	2008 - 2012	#1, #2, #3, #5, #6	static	57	---	yes	yes	CSC 2-01	yes	no	CSC 4-06
New in V76	Volkswagen	Sharan	2016 - 2023	#1, #2, #3, #5, #6	static	76	---	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Volkswagen	T5 (7E/7F)	2009 - 2015	#1, #2, #3, #5, #6	static	57	---	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Volkswagen	T6 (SG/SF)	2015 -	#1, #2, #3, #5, #6	static	57	---	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Volkswagen	Tiguan (AD)	2016 -	#1, #2, #3, #5, #6	static	57	---	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Volkswagen	Tiguan Allspace (BW)	2017 -	#1, #2, #3, #5, #6	static	57	---	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Volkswagen	Touareg (7L)	2006 - 2010	#1, #2, #3, #5, #6	static	57	---	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Volkswagen	Touareg (7P)	2010 -	#1, #2, #3, #5, #6	static	57	---	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Volkswagen	Touareg (CR)	2018 -	#1, #2, #3, #5, #6	static	57	---	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Volkswagen	Touran (5T)	2015 -	#1, #2, #3, #5, #6	static	57	---	yes	yes	CSC 2-01	yes	no	CSC 4-06

6 Vehicle Coverage Laser Sensor

Basic precondition: mega macs PC, 77, 66 (until V70), 56, 42SE, ONE, X, PC SE, S 20

Calibration required:

- #1 laser sensor removed and installed
- #2 fault code
- #3 suspension structure modified / adjusted
- #4 lock carrier loosened / wrongly adjusted
- #5 bumper bracket loosened / wrongly adjusted
- #6 damage of bumper bracket or lock carrier

Status Version	Manufacturer	Model	Year	Calibration required at	Available since version	Equipment for positioning		Equipment for calibration
						CSC-Tool	System mount	Targets
	Audi	A6 (4A)	2018 -	#1, #2, #3, #4, #5, #6	56	yes	yes	CSC 5-01
	Audi	A7 (4K)	2018 -	#1, #2, #3, #4, #5, #6	56	yes	yes	CSC 5-01
	Audi	A8 (4N)	2017 -	#1, #2, #3, #4, #5, #6	56	yes	yes	CSC 5-01
	Audi	Q7 (4M)	2019 -	#1, #2, #3, #4, #5, #6	56	yes	yes	CSC 5-01
	Audi	Q8 (4M)	2019 -	#1, #2, #3, #4, #5, #6	56	yes	yes	CSC 5-01
	Audi	e-tron (GE)	2019 -	#1, #2, #3, #4, #5, #6	59	yes	yes	CSC 5-01

7 Vehicle Coverage Front Corner Radar

Basic precondition: mega macs PC, 77, 66 (until V70), 56, 42SE, ONE, X, PC SE, S 20

Calibration required:

- #1 after removal/installation of radar sensor
- #2 replacement of radar sensor / ECU for front edge radar
- #3 after accident repair in the area of the radar sensor
- #4 after height adjustment of suspension
- #5 fault code
- #6 removal and installation

Status Version	Manufacturer	Model	Year	Calibration required at	Calibration type	Available since version	Notes	Equipment for positioning				Equipment for calibration
								CSC-Tool	Rear Cam Kit I Basic profile	Rear Cam Kit I Basic reference panel	Rear Cam Kit I Addition Profile	Radar reflector
	Audi	A6 (4A)	2018 -	#1, #2, #3, #5, #6	dynamic & static	59	static or dynamic calibration possible	yes / no	yes	CSC 2-01	yes	CSC 4-06
	Audi	A7 (4K)	2018 -	#1, #2, #3, #5, #6	dynamic & static	59	static or dynamic calibration possible	yes / no	yes	CSC 2-01	yes	CSC 4-06
	Audi	A8 (4N)	2017 -	#1, #2, #3, #5, #6	dynamic & static	59	static or dynamic calibration possible	yes / no	yes	CSC 2-01	yes	CSC 4-06
	Audi	e-tron (GE)	2019 -	#1, #2, #3, #5, #6	static	59		yes	yes	CSC 2-01	yes	CSC 4-06
	Audi	e-tron GT (F8)	2021 -	#1, #2, #3, #5, #6	dynamic & static	63	static or dynamic calibration possible	yes / no	yes	CSC 2-01	yes	CSC 4-06
	Audi	Q7 (4M)	2015 -	#1, #2, #3, #5, #6	dynamic & static	59	static or dynamic calibration possible	yes / no	yes	CSC 2-01	yes	CSC 4-06
	Audi	Q8 (4M)	2018 -	#1, #2, #3, #5, #6	dynamic & static	59	static or dynamic calibration possible	yes / no	yes	CSC 2-01	yes	CSC 4-06
	Audi	Q8 e-Tron (GE)	2023 -	#1, #2, #3, #5, #6	dynamic & static	71	static or dynamic calibration possible	yes / no	yes	CSC 2-01	yes	CSC 4-06
	Kia	Optima	2015 -	#1, #2, #3, #4, #5, #6	static	70	---	no	yes	no	no	CSC 4-04
	Lexus	NX	2021 -	#1, #2, #3, #4, #5, #6	static	70	---	no	yes	no	no	CSC 4-05
	Mazda	3 (BP)	2019 -	#1, #2, #5, #6	dynamic	59	---	no	no	no	no	no
	Mazda	CX-30 (DM)	2019 -	#1, #2, #5, #6	dynamic	59	---	no	no	no	no	no
	Mazda	CX-60 (KH)	2022 -	#1, #2, #5, #6	dynamic	70	---	no	no	no	no	no
	Mazda	MX-30 (DR)	2020 -	#1, #2, #5, #6	dynamic	59	---	no	no	no	no	no
	Peugeot	408II	2023 -	#1, #2, #4, #5, #6	dynamic	75	---	no	no	no	no	no
	Toyota	C-HR	2023 -	#1, #2, #3, #4, #5, #6	static	74	---	yes	yes	no	no	CSC 4-05
	Toyota	Prius Plug-In Hybrid	2023 -	#1, #2, #3, #4, #5, #6	static	72	---	yes	yes	CSC 2-01	yes	CSC 4-06
	Volkswagen	Touareg (CR)	2018 -	#1, #2, #3, #5, #6	static	59	---	yes	yes	CSC 2-01	yes	CSC 4-06

HELLA GUTMANN SOLUTIONS GMBH

Am Krebsbach 2

79241 Ihringen

GERMANY

Phone: +49 7668 9900-0

Fax: +49 7668 9900-3999

info@hella-gutmann.com

www.hella-gutmann.com

© 2025 HELLA GUTMANN SOLUTIONS GMBH