



Hella Gutmann Solutions A/S  
2619 Lillehammer  
TLF: +47 35 93 40 06  
Mail: support@hella-gutmann.no

# Hotline info

## Bil info

Bilmerke:	Renault
Model:	Master
Årsmode:	2011-
Km stand:	ikke relevant
Motorkode:	M9T B6

## Bilteknisk problem

- Bilen mangler ladetrykk
- Slinger på innsuget suger seg flate under gasspådrag, men ikke med avmontert partikelfilter
- Diff. trykk i partikelfilteret er i orden

## Feilkoder

Ingen feilkoder registreret i motorstyring



Hella Gutmann Solutions A/S  
2619 Lillehammer  
TLF: +47 35 93 40 06  
Mail: support@hella-gutmann.no



# Hotline info



## Løsning

- Lukkespjeld i EGR ventil er brekt av akslen, og sitter fast i turbinhjulet på turboen.

