



Hella Gutmann Solutions A/S
2619 Lillehammer
TLF: +47 35 93 40 06
Mail: support@hella-gutmann.no



Hotline info

Bil info

Bilmerke:	Alle diesel biler
Model:	SID 807 CR anlegg
Årsmode:	Ikke relevant
Km stand:	Ikke relevant
Motorkode:	Ikke relevant

Bilteknisk problem

- Støy fra motorrum
- Dyse støy
- Forbrenningsstøy

Feilkoder

Ingen feil i feillager



Hella Gutmann Solutions A/S
2619 Lillehammer
TLF: +47 35 93 40 06
Mail: support@hella-gutmann.no

Hotline info



Løsning

- Skift ikke komponenter før disse trinn er utført
- Dyserne skal opplæres på nytt (zero fuel compensation)
- Dette gjøres manuelt ute veien

